

FIELD REPORT

Project:	Number:	065
	Date:	11.28.2014
	Temperature:	High 30's
FFKR Proj #:	Weather:	Cloudy and High Wind
Contractor:		

Report Author: Mark Wightman

Present on Site: Mark Wightman

Work in

Progress: Carpet, plank and sheet vinyl flooring is being installed on 5th and 4th floor of B building. Corner guards, wall base and wall protection bumpers are also going in.

Observations Made:

- 141128-01 **Corner guards:** some corner guards are installed flush with the carpet or rubber base, and some are installed so that there is a gap between the two materials. The intent was for these materials to be flush as diagramed and noted in the product's specifications and installation documents. Please install them per manufacturer's recommendations.
- 141128-02 **Rubber Base Notch:** Notching the rubber base over the thresholds is ok, but you need to make sure that the rubber base is stuck to the wall and won't have opportunity to be peeled off.
- 141120-03 **Rubber Base – Preformed Corners:** The preformed corners aren't seaming well. They also need to be stuck to the wall better. Some of the spaces have a "site installed base." I assume this is done to as an option for us to review to replace the preformed corners. If we proceed with this option, we need to limit the under turn on the corner's bottom lip, and the white crease mark.
- 141120-04 **Carpet Base:** Please make sure the carpet base is glued to the wall in all places. Gaps like image shown will not be accepted.
- 141120-05 **Sheet Vinyl Flooring:** This is looking really good, and is being installed per our Model room Mock up discussion with cut seam put at the back of the space and allowing a full tile at threshold.
- 141128-06 **Luxury Vinyl Plank:** The LVT flooring in the kitchens is also looking really good and is being installed per direction.
- 141128-07 **Accent Paint:** The accent paint at the end of the Halls is not
-

correct. Currently each floor has the door alcove paint (red, green, teal, yellow) painted in the location that "W2," Sycamore Tan is supposed to be painted. These colored walls only happen at the door alcoves, living room walls and inside the stair landings. See Sheet D1/A-713B for reference. It is also desired to have the accent paint extended above the door to expansion joint.

Supporting Documents: See Attached Photos

Item 01:



Item 02:



Item 03:





Item 04:



Item 07:



